

## Exhibit Summary

### **Dairy Facility:** Faria Dairy, DP-923

**Description:** Maps submitted by the permittee to the department indicate that two monitoring wells have been mislabeled such that a well intended to be hydrologically downgradient of a contamination source was switched with one that is intended to be hydrologically upgradient of the facility.

On the maps dated 11/12/2004 and 10/16/2006, monitoring well MW-2 is intended to be located hydrologically downgradient of a stormwater impoundment and monitoring well MW-1 is intended to be located hydrologically upgradient of the facility. The map dated 10/08/2008 has the wells reversed such that MW-1 is intended to be located hydrologically downgradient of a stormwater impoundment and MW-2 is intended to be located hydrologically upgradient of the facility.

---

### **Dairy Facility:** Carter's Milk Factory, DP-926

**Description:** Maps submitted by the permittee to the department indicate that two monitoring wells have been mislabeled such that a well intended to be hydrologically downgradient of a contamination source was switched with one that is intended to be hydrologically upgradient of the facility.

On the map dated 05/22/2003, monitoring well MW-5 is intended to be located hydrologically downgradient of the land application area and monitoring well MW-4 is intended to be located hydrologically upgradient of the facility. The map dated 06/09/2004 has the wells reversed such that MW-4 is intended to be located hydrologically downgradient of the land application area and MW-5 is intended to be located hydrologically upgradient of the facility.

---

### **Dairy Facility:** Ridgecrest Dairy, DP-1346

**Description:** Maps submitted by the permittee to the department indicate that two monitoring wells have been mislabeled such that a well intended to be hydrologically downgradient of a contamination source was switched with one that is intended to be hydrologically upgradient of the facility.

On the map dated 09/01/2004, monitoring well MW-1 is intended to be located hydrologically downgradient of the land application area and monitoring well MW-3 is intended to be located hydrologically upgradient of the facility. The map dated 02/19/2009 has the wells reversed such that MW-3 is intended to be located hydrologically downgradient of the land application area and MW-1 is intended to be located hydrologically upgradient of the facility.




---

**Dairy Facility:** Nutt Dairy, DP-1391

**Description:** Maps submitted by the permittee to the department indicate that two monitoring wells have been mislabeled such that a well intended to be hydrologically downgradient of a contamination source was switched with one that is intended to be hydrologically upgradient of the facility.


On the map submitted in 2003, monitoring well MW-2 is intended to be located hydrologically downgradient of the wastewater impoundment and monitoring well MW-1 is intended to be located hydrologically upgradient of the facility. The maps submitted in 2005 and 2009 have the wells reversed such that MW-1 is intended to be located hydrologically downgradient of the wastewater impoundment and MW-2 is intended to be located hydrologically upgradient of the facility.



Title:	Farla East Dairy	DP-923	Sheet No
	Overall Site Layout		1/1
Date:	11/12/2004	DWG/Doc Ref	Scale 1" = 1000'



<b>Title:</b> Faria Dairy East Overall Site Layout		<b>DP-923</b>
<b>Date:</b> 10/16/2006	<b>DWG / Doc Ref</b> Not to Scale	<b>Sheet No</b> 1/1



# GROUND WATER

DEC 07 2009

BUREAU

**Enviro Compliance Services, Inc.**  
 Office: (505) 762-9674 Fax: (505) 762-3749  
 Providing Management Assistance for Environmental Compliance Since 1981


Title:	Faria Dairy East Overall Site Layout	DP-923
Date:	10/08/2008	DWG/Doc Ref Not to Scale
		Sheet No 1/1

DEC 20 2006

BUREAU

Section 5  
T 3S; R 36E

47




Title:	Carter's Milk Factory Overall Site Layout	DP-926
Date:	5/22/2003	Sheet No 1/1
	DWG/Doc Ref	

**Enviro Compliance  
Services, Inc.**

Office: (505) 762-9674 Fax: (505) 762-3749  
... and Assistance for Environmental Compliance Since 1981





Section 5  
T 3S; R 35E




**Enviro Compliance  
Services, Inc.**

Office: (505) 762-9674 Fax: (505) 762-3749

Providing Management Assistance for Environmental Compliance Since 1981

Title: <b>Carter's Milk Factory Overall Site Layout</b>		DP-926
Date: <b>6/9/2004</b>	DWG/Doc Ref Scale 1" = 700'	Sheet No 1/1



Section 31  
T 4N; R 37E

GROUND WATER

AUG 30 2007

BUREAU


**Enviro Compliance  
Services, Inc.**

Office: (505) 762-9674 Fax: (505) 762-3749

Providing Management Assistance for Environmental Compliance Since 1981

Title: Ridgecrest Dairy Overall Site Layout		DP-1346
Date: 9/1/2004	DWG/Doc Ref Scale 1"=800'	Sheet No 1/1





Section 31  
T 4N; R 37E

### GROUND WATER

**Enviro Compliance Services, Inc.**

Office: (505) 762-9674 Fax: (505) 762-3749


Providing Management Assistance for Environmental Compliance Since 1981

SEP 02 2009

BUREAU

Title: <b>Ridgecrest Dairy</b>		DP-1346
Overall Site Layout		
Date: <b>2/19/2009</b>	DWG/Doc Ref Scale 1"=800'	Sheet No 1/1

22-141 50 SHEETS  
22-142 100 SHEETS  
22-144 200 SHEETS




Monitoring Well #1  
Lat. 32° 35' 25.6"  
Long. 107° 22' 35.9"  
Elevation. 4,506 ft  
Depth to Water 138.5 ft.

Monitoring Well #2  
Lat. 32° 35' 21.3"  
Long. 107° 22' 22.0"  
Elevation 4,498 ft.  
Depth to Water 66.4 ft.

0 250 500  
(feet)

Submitted ~ 2003



Submitted ~2005



# Nutt Dairy Site Map

Discharge Permit: DP# 1391  
Permitted discharge: 25,000 GPD

T20S, R5W, Sec. 5 & 8  
Hatch, Luna County, NM  
32°35'14", 107°22'25"

Monitoring wells




functional

*submitted  
~2009*

4500

Elevation contours, feet  
above mean sea level



GLORIETA GEOSCIENCE, INC.  
P.O. Box 5727 Santa Fe, NM 87502  
(505) 983-5446 Fax (505) 983-6482  
E-mail: ggi@glorietageo.com  
Web Address: www.glorietageo.com

Contact Info: Nutt Dairy, P.O. Box 751, Hatch, NM 87937 Office: 505-267-9217 Cell: 505-869-0837